



RIPJAWS MX780 Changelog

Software Version: 1.03

Firmware Version: 21

Notes:

- Fixed a bug where modifier keys do not work in macros.